Scope of	Work for Prope	rty Loca	ted	at:			<u>4144</u>	North 14	th Street	1		
	Property is: Sir	ngle Famil	y	7	Dup	olex		Other □			 	
Date:	12/21/2015		_									
ake no respo	ninimum requirement on sibility for problems distributed by private lenders, insu	scovered aft	ter th	e ins	pectio	n dat	e, or for	omissions thr	ough error or	oversight.		
Exterior (Condition Repor	t										
Location Site	Required Work Landscaping		n/a	7	Yes		Note/ Self H	Comments elp			\$	Cost
	Steps/Handrails		n/a	7	Yes						\$	
	Service walks		n/a		Yes	7	patch	and repair			\$	1,000.00
	Fencing		n/a	7	Yes						\$	
	Parking		n/a	7	Yes						\$	
	Retaining walls		n/a	V	Yes						\$	
	Other		n/a		Yes						\$	
_	Other		n/a		Yes						\$	
Garage	Singles: repair		n/a	7	Yes						\$	
	Shingles: Roof over e	existing	n/a	7	Yes						\$	
	Shingles:Tear off & re	e-roof	n/a		Yes	V					\$	1,500.00
	Gutters/downspouts		n/a		Yes	V					\$	500.00
	Flashing		n/a	V	Yes						\$	
	Eaves		n/a	7	Yes						\$	
	Siding		n/a	7	Yes						\$	
	Doors		n/a	7	Yes						\$	
	Windows		n/a	7	Yes						 \$	
	Slab		n/a	7	Yes						 \$	
	Paint		n/a	7	Yes						 \$	
	Electrical		n/a	7	Yes						 \$	
_	Other		n/a		Yes						\$	
Porches	Roof		n/a	7	Yes						\$	
	Deck-upper		n/a	7	Yes						\$	
	Decklower		n/a	7	Yes						\$	
	Steps/handrails		n/a	7	Yes		•				\$	
	Ceiling		n/a	7	Yes						\$	
	Guardrails		n/a	7	Yes						 \$	
	Structural		n/a	7	Yes						\$	
	Paint		n/a	V	Yes						 \$	

n/a □ Yes ☑ masonry repair

Other

500.00

\$

House

Chimney	n/a □	Yes ☑	tuck point and flash	\$ 450.00
Shingles: repair	n/a ☑	Yes □		\$
Shingles: Roof over existing	n/a ☑	Yes □		\$
Shingles:Tear off & re-roof	n/a □	Yes ☑		\$ 7,500.00
Gutters/downspouts	n/a □	Yes ☑		\$ 1,500.00
Flashing	n/a ☑	Yes □		\$
Eaves	n/a □	Yes ☑	fasica and soffit repair	\$ 500.00
Siding	n/a _□	Yes ☑	tuck point	\$ 500.00
Storm Doors	n/a ☑	Yes □		\$
Prime ("main") Doors	n/a □	Yes ☑		\$ 750.00
Storm Windows	n/a ☑	Yes □		\$
Prime ("main") Windows	n/a ☑	Yes □		\$
Paint	n/a 🗆	Yes ☑	all trim	\$ 1,500.00
Foundation	n/a 🔽	Yes □		\$
Electrical	n/a ☑	Yes □		\$ _
Other	n/a □	Yes □		\$ _
Other	n/a □	Yes □		\$
Other	n/a □	Yes □		\$
Other	n/a □	Yes □		\$

Exterior: Estimated Cost:* \$
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

16,200.00

Interior Co	ondition Report						
	Unit: Entire unit (single family) Upper unit of duplex	✓			Lower unit of duplex Other		
Mechanical Heating	Required Work						
	Repair/replace boiler	n/a ☑	Yes			\$	
	Repair radiation	n/a ☑	Yes			\$	
	Repair/replace furnace	n/a ☑	Yes			\$	
	Repair ductwork	n/a ☑	Yes			\$	
	Replace thermostat	n/a ☑	Yes			\$	
	Repair/replace grilles	n/a ☑	Yes			\$	
Electrical	Tune boiler/furn. insp ht exchang	€n/a □	Yes	7	_	\$	250.00
Electrical	Repair/replace receptacles	n/a 🗆	Yes	7	_	\$	100.00
	Repair/replace switches	n/a □	Yes	7		\$	100.00
	Repair/replace fixtures	n/a □	Yes	V		\$	300.00
	Install outlets and circuits	n/a □	Yes	7		\$	500.00
	Install outlets and circuits	n/a ☑	Yes			\$	
	Install outlets and circuits	n/a ☑	Yes			\$	
	Install outlets and circuits	n/a ☑	Yes			\$	
	Upgrade service	n/a _☑	Yes		_	\$	
	Other	n/a □	Yes			\$	
Plumbing	Other	n/a 🔲	Yes		_	\$	
Fidilibilig	Repair/replace kitchen sink	n/a □	Yes		_	\$	
	Repair/replace kitchen sink fauce	n/a 🔲	Yes		_	\$	
	Repair/replace tub	n/a □	Yes			\$	
	Repair/replace tub faucet	n/a □	Yes			\$	
	Repair/replace toilet	n/a □	Yes			\$	
	Repair/replace lavatory	n/a □	Yes			\$	
	Repair/replace lavatory faucet	n/a □	Yes			\$	
	Repair/replace wash tub	n/a □	Yes			\$	
	Repair/replace wash tub faucet	n/a □	Yes			\$	
	Unclog piping:	n/a □	Yes			\$	
	Repair drain/waste/vent piping	n/a □	Yes	7		\$	1,000.00
	Repair water piping	n/a □	Yes	7		\$	1,000.00
	Repair/replace water heater	n/a _□	Yes	√		\$	750.00
	Other	n/a □	Yes	√	complete kitchen	\$	1,500.00
	Other	n/a □	Yes	V	complete bath	\$	2,500.00

Windows										
	Replace broken glass	n/a □	Yes	√	_	\$	200.00			
_	Repair or replace sash	n/a ☑	Yes		=	\$				
Doors	Repair or replace doors	n/a ☑	Yes			\$				
	Repair or repl. locks/latches	n/a ☑	Yes		Self Help	\$				
Walls/Ceiling			.,		· · · · · · · · · · · · · · · · · · ·					
	Repair or repl. @ defective	n/a □	Yes	√	=	\$	2,000.00			
Paint	Repair or repl. @ defective	n/a □	Yes	7		\$	500.00			
Fire Safety	· · · · ·									
ine calety	Install smoke/CO alarm:bsmt.	n/a □	Yes	V	Self Help	\$	50.00			
	Install smoke/CO alarm: 1st flr.	n/a <u></u> □	Yes	7	Self Help	\$	50.00			
	Install smoke/CO alarm: 2nd flr.	n/a □	Yes	V	Self Help	\$	50.00			
Handrails	Repair/replace defective	n/a □	Yes		Self Help	\$	120.00			
Stairs	Tropan/Topiaco doloctivo	,u <u> </u>				Ψ	120.00			
Fl	Repair defective	n/a <u></u> ✓	Yes		_	\$				
Floors	Repair defective	n/a □	Yes	IJ		\$	2,000.00			
Other	Tiopan dolocity	.,, u	1 00		-	Ψ	2,000.00			
		n/a □	Yes			\$				
		n/a □	Yes			\$				
	_	n/a □	Yes			\$				
		n/a □	Yes			\$				
					Interior: Estimated Cost:	\$	12,970.00			
					Total Exterior and Interior Cost:*	\$	29,170.00			
	to core as perhaps and peak Ashiral peaks may your Calif halo will reduce the amount									

Inspected by: Andy Yeager Date: 12/21/15

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.